Dart Aerospace Ltd. Tuesday, 15/07/2008 1:04:41 PM **Process Sheet** : INSULATION FILTER Customer : CU-DAR001 Dart Helicopters Services **Drawing Name** Job Number : 38808 **Estimate Number** : 10936 P.O. Number : D2301 Part Number This Issue : 15/07/2008 S.O. No. : : D2301 REV A **Drawing Number** : NC Prsht Rev. **Project Number** : N/A : 28/04/2008 First Issue Type : SMALL /MED FAB : A **Drawing Revision** : 30572 **Previous Run** Material **Due Date** : 15/05/2008 Qty: 4 Um: Written By Checked & Approved By Comment : Est: A05.03.16 New Issue KJ/JLM **Additional Product** Job Number: Seq. #: **Machine Or Operation:** Description: D2412 1.0 Insulation Filter Comment: Qty.: 1.7281 sf(s)/Unit Total: 6.9124 sf(s) Insulation Filter Cut as per Dwg D2301 Material: High Temp Fiberglass cloth 9383 Heat Treatment meets MIL-C-20079G(D2412 Batch M104845 B 31028 Identify as D2301 2.0 SMALL FAB SMALL & MEDIUM FAB RESOURCE 1 Comment: SMALL & MEDIUM FAB RESOURCE 1 Cut as per Dwg D2301 QC6 3.0 DIMENSIONAL CHECK Comment: DIMENSIONAL CHECK 4.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1

Identify and Stock

Location: PRP.

QC21 5.0

FINAL INSPECTION/W/O RELEASE

Comment: FINAL INSPECTION/W/O RELEASE



4 8-10.07

Each

Page 1

Form: rprocess





-	PREPARED		DART .	AERO ACCESSORIES	INC				
- 1			į.		1140				
	_B. Williams		VICTORIA INTERNATIONAL AIRPORT, CANADA						
	CHECKED	APPROVED			REV. A				
			D2301	CHEET	1 OF 1				
-	September 1		0200:	J. I.C.	, 0, ,				
	DATE		TITLE		SCALE				
1	Oct 25 1	994	INSHIATIO	ON FILTER					

13.500 MATERIAL: HIGH TEMPERATURE FIBERGLASS CLOTH 9383 HEAT TREATMENT, MEETS MIL—C—200796 SERVICE TEMPERATURE 1000F TYPE "E" GLASS FIBER WEIGHT 16 oz CUT 18 X 13.5 SOURCE: TEMPRO TEC Inc 2025—9383 -16,000

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES			T -	Approval	Approval
DATE	STEP	PROCEDURE CHANGE		Date _	Qty	Chief Eng / Prod Mgr	Approval QC Inspector
		₩. ^{**}					

Part No: D2301 PAR #: NA Fault Category: Rad Packaging NCR: Yes No DQA: Date: 00/009.

Day-575043 Date: 00/009

NCR: 38808		WORK ORDER NON-CONFORMANCE (NCK)								
		Description of NC Section A	Corrective Action Section B			Verification	Approval	Approval		
DATE	STEP		Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector		
08 08 48	2.0	The incurrect material was cut, for the cyclur. Cut 902 glass instead of Fiberglass cloth 9383. R. C. Employee grabback the incurrect material, lack of Attention.		Assive 902 cloth to composite Assive for any possible re-work. Brys and be identified with BH ! P/N.	W.0.01	05.1012	losiun	65-48 B3		
		R.C. Employee grabbed the incorrect material, lack of Attention.	A051W2	WILL BE : P/N.		/05.1012 02.110/03	t	. '		
		,								

NOTE: Date & initial all entries